





ΜΑΜΟΤΟΥΧ





STEP 1





STEP 2





STEP 3



STEP 4




STEP 5




STEP 6




4x



STEP 7



2x




STEP 8






12



1x






STEP 9




STEP 10





STEP 11




STEP 12




STEP 13






STEP 14






STEP 15





STEP 16





STEP 17



STEP 18




STEP 19





STEP 20

3
2x




STEP 21



2x





STEP 22





STEP 23 A





STEP 23 B





STEP 24 A





STEP 24 B





STEP 25 A





STEP 25 B




STEP 26 A



STEP 26 B





STEP 27 A





Connect on **all four legs** in the 4th hole from the bottom.


STEP 27 B




STEP 27 C



STEP 28 A




1x 1x




STEP 28 B



2x




STEP 28 C



1x

1x




STEP 28 D





1x



2x





STEP 28 E





STEP 28 F




STEP 28 G





STEP 28 H





STEP 28 I





STEP 28 J




STEP 28 K



STEP 28 L





STEP 29



Assembled head should look like this

STEP 30





Connect the **Ultrasonic** sensor to **Port 4**.


Connect the **Motor** sensor to **Port A**.

BONUS




1

REMOVE THE FEET




NXT




BONUS 2




BONUS 3






BONUS 4



4x  4x  3  4x  4x  4x



1 
2 
3 
Bushing
x4



DONE!

